







































Lužnice 10, 344 01 Domažlice

CZECH REPUBLIC

Tel.: +420 379 723 915, Fax: +420 379 725 868

[www.atd-elektronik.cz](http://www.atd-elektronik.cz) [info@atd-elektronik.cz](mailto:info@atd-elektronik.cz)







|              |   |   |   |   |   |   |
|--------------|---|---|---|---|---|---|
| Popis        | <b>MC 100</b>   | <b>MC 101</b>   | <b>MC 123</b>   | <b>MC 200</b>   | <b>MC 201</b>   | <b>MC 230</b>   |
|              |    |    |    |    |     |    |
| RM<br>p. póů | 5; 5,08; 7,62<br>2 - 24   | 5; 5,08; 7,62;<br>2 - 22  | 5,08<br>2 - 20  | 7,5<br>2 - 18   | 5<br>2 - 22   | 5; 5,08<br>2 - 8  |
| Popis        | <b>MC 310</b>   | <b>MC 311</b>   | <b>MC 420</b>   | <b>MC 421</b>   | <b>MC 520</b>   | <b>MC 521</b>   |
|              |    |    |    |    |    |    |
| RM<br>p. póů | 5; 5,08<br>2 - 24   | 5; 5,08<br>2 - 24   | 3,5; 3,81<br>2 - 24   | 3,5; 3,81<br>2 - 24   | 3,5; 3,81<br>2 - 24   | 3,5; 3,81<br>2 - 24   |
| Popis        | <b>MC 600</b>   | <b>MC 605</b>   | <b>MC 700</b>   | <b>MC 705</b>   | <b>ME 010</b>   | <b>ME 010A</b>  |
|              |  |  |  |  |  |  |
| RM<br>p. póů | 3,5<br>2 - 40   | 3,5<br>2 - 40   | 2,5<br>2 - 24   | 5,0<br>2 - 24   | 5,0; 5,08<br>2 - 24   | 5,08<br>2 - 10  |
| Popis        | <b>ME 020</b>   | <b>ME 030</b>   | <b>ME 030</b>   | <b>ME 040</b>   | <b>ME 040</b>   | <b>ME 050</b>   |
|              |  |  |  |  |   |  |
| RM<br>p. póů | 5,0; 5,08; 7,62<br>2 - 24   | 3,5; 3,81<br>2 - 24   | 5,0; 5,08; 7,62<br>2 - 24   | 3,5; 3,81;<br>2 - 24  | 5,0; 5,08; 7,62<br>2 - 24   | 3,5; 3,81<br>2 - 24   |
| Popis        | <b>ME 050</b>   | <b>ME 060</b>   | <b>ME 060</b>   | <b>ME 110</b>   | <b>ME 150</b>   | <b>ME 230</b>   |
|              |  |  |  |  |  |  |
| RM<br>p. póů | 5,0; 5,08; 7,62<br>2 - 16   | 3,5; 3,81<br>2 - 24   | 5,0; 5,08; 7,62<br>2 - 22   | 5,0; 5,08<br>4 - 6  | 5,0; 5,08<br>8 - 48   | 5,0; 5,08<br>4 - 48   |

|       |   |   |   |   |   |   |
|-------|---|---|---|---|---|---|
| Popis | <b>ME 630</b>   | <b>ME 960</b>   | <b>MPC 301</b>  | <b>MPX 120</b>  | <b>MT 300</b>   | <b>MT 300</b>   |
|       |  |  |  |  |  |  |







|               |                     |               |               |                     |                          |                           |
|---------------|---------------------|---------------|---------------|---------------------|--------------------------|---------------------------|
| RM<br>p. póľů | 5,0; 5,08<br>2 - 24 | 3,5<br>2 - 40 | 5,0<br>2 - 16 | 5,0; 5,08<br>4 - 48 | 5,0; 5,08; 7,5<br>2 - 24 | 7,62; 10; 10,16<br>2 - 16 |
|---------------|---------------------|---------------|---------------|---------------------|--------------------------|---------------------------|

|       |   |   |   |   |   |   |
|-------|---|---|---|---|---|---|
| Popis | <b>MT 420</b>   | <b>MX 122</b>   | <b>MX 222</b>   | <b>MX 322</b>   | <b>MX 422</b>   | <b>MX 522</b>   |
|       |  |  |  |  |  |  |






|               |                     |                             |                             |                |                |               |
|---------------|---------------------|-----------------------------|-----------------------------|----------------|----------------|---------------|
| RM<br>p. póľů | 5,0; 5,08<br>2 - 24 | 5,08; 7,62; 10,16<br>2 - 24 | 5,08; 7,62; 10,16<br>2 - 24 | 2,54<br>2 - 24 | 2,54<br>2 - 24 | 3,5<br>2 - 24 |
|---------------|---------------------|-----------------------------|-----------------------------|----------------|----------------|---------------|

|       |   |   |   |   |   |   |
|-------|---|---|---|---|---|---|
| Popis | <b>MX 732</b>   | <b>MX 822</b>   | <b>MX 832</b>   | <b>MWX 200</b>  | <b>MWX 200</b>  | <b>MWX 211</b>  |
|       |  |  |  |  |  |  |

|               |              |                |                |                           |                     |                           |
|---------------|--------------|----------------|----------------|---------------------------|---------------------|---------------------------|
| RM<br>p. póľů | 5,0<br>2 - 3 | 4,57<br>2 - 10 | 5,08<br>2 - 24 | 3,81; 5,0; 5,08<br>2 - 26 | 7,5; 7,62<br>2 - 20 | 3,81; 5,0; 5,08<br>2 - 24 |
|---------------|--------------|----------------|----------------|---------------------------|---------------------|---------------------------|

|       |   |   |   |   |   |   |
|-------|---|---|---|---|---|---|
| Popis | <b>MWX 211</b>  | <b>MWX 211</b>  | <b>MWX 300</b>  | <b>MWX 300</b>  | <b>MWX 302</b>  | <b>MWX 305</b>  |
|       |  |  |  |  |  |  |

|               |                     |                       |                          |                           |                          |                           |
|---------------|---------------------|-----------------------|--------------------------|---------------------------|--------------------------|---------------------------|
| RM<br>p. póľů | 7,5; 7,62<br>2 - 24 | 10,0; 10,16<br>2 - 24 | 5,0; 5,08; 7,5<br>2 - 24 | 7,62; 10; 10,16<br>2 - 24 | 5,0; 5,08; 7,5<br>2 - 24 | 7,62; 10; 10,16<br>2 - 24 |
|---------------|---------------------|-----------------------|--------------------------|---------------------------|--------------------------|---------------------------|

|       |   |   |   |   |  |   |
|-------|---|---|---|---|--|---|
| Popis | <b>ME 250</b>   | <b>ME 411</b>   | <b>ME 421</b>   | <b>ME 430</b>   | <b>ME 530</b>  | <b>ME 710</b>   |
|       |  |  |  |  |  |  |

|               |                     |                |                |                |                |                     |
|---------------|---------------------|----------------|----------------|----------------|----------------|---------------------|
| RM<br>p. póľů | 5,0; 5,08<br>4 - 48 | 3,81<br>2 - 24 | 3,81<br>2 - 24 | 3,81<br>2 - 24 | 3,81<br>4 - 40 | 5,0; 5,08<br>2 - 22 |
|---------------|---------------------|----------------|----------------|----------------|----------------|---------------------|

|       |   |   |   |   |  |   |
|-------|---|---|---|---|--|---|
| Popis | <b>ME 710</b>   | <b>MB 632</b>   | <b>MB 642</b>   | <b>MB 652</b>   | <b>MB 662</b>  | <b>MB 920</b>   |
|       |  |  |  |  |  |  |

|               |                     |                     |                     |                     |                     |               |
|---------------|---------------------|---------------------|---------------------|---------------------|---------------------|---------------|
| RM<br>p. póľů | 7,5; 7,62<br>2 - 24 | 5,0; 5,08<br>2 - 16 | 5,0; 5,08<br>4 - 32 | 5,0; 5,08<br>4 - 32 | 5,0; 5,08<br>6 - 48 | 9,52<br>2 - 3 |
|---------------|---------------------|---------------------|---------------------|---------------------|---------------------|---------------|